

TOWN OF WASHBURN LANDFILL OVERSIGHT

WITH THE CLOSING OF THE WASHBURN (MAPLE HILL SEC 29) LANDFILL ONCE USED BY THE CITY OF WASHBURN, THE TOWN OF BAYVIEW AND OUR TOWN'S PEOPLE IT IS IMPERATIVE THAT WE MONITOR THE SITE FOR THE SAFETY OF OUR SELVES AND THOSE IN THE FUTURE.

THE FOLLOWING I BELIEVE SHOULD TAKE PLACE:

1. THE 3 MONITORING WELL'S INFORMATION SHOULD BE REVIEWED AT LEAST ANNUALLY WITH A REPORT GIVEN AT OUR ANNUAL TOWN MEEETING.
2. THE CLAY CAP SHOULD BE INSPECTED FOR WINTER DAMAGE DUE TO FROST HEAVING AND/OR OTHER SETTLING TWICE A YEAR ONCE IN THE SPRING (MAY) AND LATER IN THE FALL. (OCTOBER). GIVE ENOUGH TIME SO REPAIRS COULD BE MADE PRIOR TO WINTER FREEZE UP AND SNOWS.
3. THAT CORRESPONDENCE OF THE FINDINGS TO ALL OF THE ABOVE BE FORWARDED TO BOTH
THE CITY OF WASHBURN (77% RESPONSIBLE) AND THE TOWN OF BAYVIEW (12%RESPONSIBLE).
IT IS IMPORTANT TO MAINTAIN THIS DIALOG AND REMIND THEM (WITH CHANGING BOARDS AND CITIZENS) THAT THEY ARE RESPONSIBLE FOR ANY CLAY-CAP RESTORATION, HAZARDOUS CLEAN-UP, ONGOING MONITORING ETC.
FOREVER!
4. FINALLY, I STRONGLY BELIEVE THAT THIS RESPONSIBILITY SHOULD BE AN ON GOING PRACTICE TO RENEW AND REMIND THE BOARD MEMBERS EACH SPRING AT OUR ANNUAL TOWN MEETING SO AS NOT TO LOSE THE IMPORTANCE OF WHAT WE ARE PROTECTING. AND ALSO AT THE TIME SWEARING-IN OF OUR NEW TOWN BOARD OFFICERS TAKES PLACE.

SUBMITTED AND RECOMMEND APPROVAL APRIL 11^{T H} 2000 AT THE ANNUAL TOWN MEETING BY STEVE BADE.